

FIG. 1





FIG. 2





300




FIG. 3A




FIG. 3B



402		404		406		
X/Y Coordinates	Calibration Sensor Value (optional)	406a		406b		406n
		Control Sensor A Value	Control Sensor B Value	Control Sensor N Value	
		Control $A_{1,1}(i.e., x=1, y=1)$	Control $B_{1,1}$		Control $N_{1,1}$	
		Control $A_{1,2}(i.e., x=1, y=2)$	Control $B_{1,2}$		Control $N_{1,2}$	
• •	• •	Control $A_{1,3}(i.e., x=1, y=3)$	Control $B_{1,3}$		Control $N_{1,3}$	
		• •	• •		• •	
		Control $A_{2,1}$	Control $B_{2,1}$		Control $N_{2,1}$	
		Control $A_{2,2}$	Control $B_{2,2}$		Control $N_{2,2}$	
• •	• •	Control $A_{2,3}$	Control $B_{2,3}$		Control $N_{2,3}$	
		• •	• •		• •	
		Control $A_{3,1}$	Control $B_{3,1}$		Control $N_{3,1}$	
		Control $A_{3,2}$	Control $B_{3,2}$		Control $N_{3,2}$	
• •	• •	Control $A_{3,3}$	Control $B_{3,3}$		Control $N_{3,3}$	
		• •	• •		• •	
		• •	• •		• •	
		• •	• •		• •	

FIG. 4